

ABSTRACT

The influences on transmission quality caused by chirp and self-phase modulation are at least largely corrected by way of an optimally set operating point of the modulator

5 (2). Suitable criteria are obtained in control loops in order to maintain the optimal setting.

Approved for Release